Release Notes for MasterConsole® Digital MDCIM and MDUTP Version 2.4.1

Date: August 01, 2023

Applicability: MDCIM-DVI, MDCIM-HDMI, MDCIM-DP, MDUTP20-VGA,MDUTP40-VGA,MDUTP60-VGA

Change Description:

We would like to notify about an upcoming firmware update for the MDUTP & MDCIM series, moving from version V2.40 to V2.41. This update aims to enhance USB compatibility when connecting MDUTP to an IBM P720 Server.

Reason for the Update:

The IBM P720 Server operates on a specific AIX 7.1 OS. When the MDUTP CIM is connected to the target IBM P720, the USB detection fails, resulting in non-functional keyboard and mouse. To address this issue, we are releasing firmware version V2.41 for the MDCIM & MDUTP series, which will significantly improve USB compatibility with IBM targets.

Effected Items

P/N	Rapid	Present FW	Updated FW
MDCIM-DVI	**100-79-3100-00**	**V2.40**	**V2.41**
MDCIM-HDMI	**100-79-3110-00**	**V2.40**	**V2.41**
MDCIM-DP	**100-79-3120-00**	**V2.40**	**V2.41**
MDUTP20-VGA	**100-79-3160-00**	**V2.40**	**V2.41**
MDUTP40-VGA	**100-79-3190-00**	**V2.40**	**V2.41**
MDUTP60-VGA	**100-79-3170-00**	**V2.40**	**V2.41**