

Release Notes for Raritan PX Firmware Version 3.2.40

Version: PX2 3.2.40 Build 43381 Release Notes, Version 4

Date: September 2, 2016

Effective: Immediately.

Applicability:

This firmware release is for Limited Availability (“LA”) on PX2 and PXE models with LED displays that exhibit a blank display screen or an all segments on (888) screen.

Release 3.2.40 General Guidelines:

Use the User Guide for PX 3.2.10. Release 3.2.40 contains all enhancements and fixes which are listed [below](#).

Some custom engineered models are not be supported by this release. Please check the **Not Supported in This Release** section [below](#). Or, contact Raritan Support if you are unsure of the model number of your unit; it is typically viewable from the GUI *Device Information* page, and is printed on a label on the side of the PDU.

Please do NOT upgrade ANY other Raritan PX model(s) to PX 3.2.40 because the unit may have been built after this release entered System Test, and it may result in the unit becoming non-functional.

Please do NOT downgrade your new PX2 firmware based models to any prior release, as these models may not be supported in previous firmware versions.

Caution: Only Power IQ releases 5.0 and higher are compatible with PX 3.2.40.

Due to significant internal enhancements in PX 3.2.40, you cannot downgrade from Release 3.2.40 build 43381 to ANY prior release. Please contact Raritan Support with any questions.

Release Status: Limited Availability (LA)

Release 3.2.40 contains all enhancements and fixes which are listed below:

1. PX2-1905-V2N1 Displays flashing on/off [CR64652]

PX2 3.2.40 Build 43381/ Release Notes, Revision V4 / September 2, 2016/ For Raritan Customers Only

This note is intended for Raritan customers only; its use, in whole or part, for any other purpose without the express written permission from Raritan, Inc. is prohibited.

Copyright ©2016 Raritan, Inc. CommandCenter, Dominion, and the Raritan company logo are trademarks or registered trademarks of Raritan, Inc. All rights reserved. Solaris and Java are trademarks of Oracle. Windows and Windows Vista are trademarks or registered trademarks of Microsoft Corporation. MAC and Safari are trademarks or registered trademarks of Apple, Inc. All other marks are the property of their respective owners.

Consult the PX 3.2.10 User Guide for more information on these firmware features:
<https://www.raritan.com/support>

Raritan PX Downloads

The following supplemental files can be downloaded via the Raritan support site

<https://www.raritan.com/support> (please select the correct product):

- FW Releases and Release notes
- Product documentation and user guides
- SNMP MIBs
- Related tools and drivers
- JSON-RPC SDK

Not Supported with PX 3.2.40:

This release has not been tested for use on all PX2/3 models. Release 3.2.40 has been formally tested for use only on PX2 and PXE models with LED displays.

If you are unsure that your model is supported by this firmware, please contact Raritan Support

Upgrade Matrix (path for upgrades):

This release is intended for firmware upgrades on PX2 and PXE models with LED displays when required.

Release Package Details:

The Release 3.2.40 package has the following components. It is a LA (Limited Availability) release.

Release 3.2.40 Package components for PX2

- PX2ReleaseNotes3_2_40_0v4” (this file)
- A firmware release (binary): pdu-px2-030240-43381.bin

General Upgrade Instructions (standalone upgrade from the browser based user interface):

PX2 3.2.40 Build 43381/ Release Notes, Revision V4 / September 2, 2016/ For Raritan Customers Only

This note is intended for Raritan customers only; its use, in whole or part, for any other purpose without the express written permission from Raritan, Inc. is prohibited.

Copyright ©2016 Raritan, Inc. CommandCenter, Dominion, and the Raritan company logo are trademarks or registered trademarks of Raritan, Inc. All rights reserved. Solaris and Java are trademarks of Oracle. Windows and Windows Vista are trademarks or registered trademarks of Microsoft Corporation. MAC and Safari are trademarks or registered trademarks of Apple, Inc. All other marks are the property of their respective owners.

- Enable JavaScript in your browser before logging into the unit to start the upgrade process.
- Follow instructions in the User Guide. Please read the entire upgrade instructions before starting an upgrade.
- If you have any questions, or cannot follow the instructions in the User Guide, please STOP and contact Raritan Technical Support for further instructions.